English - Safety Instructions:

HOBBES SURVLtest

13.01.3291

- The tester is designed for use in compliance with local electrical regulations and should not be used in locations unsuitable for electrical devices, such as hospitals or gas stations.
- To prevent functional decline or damage, avoid exposing the product to moisture or splashing water.
- Keep the exposed parts of the tester free from dust and liquids.
- During transportation and use, avoid violent collisions or vibrations to prevent damage to components and functionality issues.
- Do not leave the tester unattended while charging. If the battery becomes excessively hot, disconnect it from the power source immediately. Do not charge the tester for more than 8 hours.
- Avoid using the tester in high-humidity environments. If the tester becomes damp, power it off immediately and disconnect any connected cables.
- The tester should not be used in environments containing flammable gases.
- Do not disassemble the tester, as there are no user-serviceable components inside. For repairs or disassembly, please contact our company's technician.
- The tester should not be used in areas with strong electromagnetic interference.
- Avoid touching the tester with wet hands or any water-laden objects.
- Do not clean the tester with detergents. Use a dry cloth for cleaning. If stubborn dirt persists, use a soft cloth moistened with water or a neutral detergent, ensuring the cloth is thoroughly wrung out.